# **A8 3D Printer Installation Guide**



# A8 Assembly Instructions

## **Attention:**

1.Please make sure the package not broken when you receive it.

2.Please check the printer parts according to the packing list.

3. Please contract your supplier if any questions.

#### **3D Printer A8 assembly parts list**

ltem	Picture	Name	QTY	Check		Picture	Name	QTY	Check
1-1		Hot bed fixed aluminum plate	1		2–1		Mainboard	1	
1-2		220mm*220mm*3mm Hot bed	1		2–2	1. e	Left Zaxisnut support	1	
1-3	$\land$	Plastic nippers	1		2–3		Right Z axis nut support	1	
1-4	ð	1.5M Power line	1		2-4		Wind mouth	1	
1-5		5mm*160mm Screwdriver	1		2–5	0	1.6M Belt	1	
1-6		Four parts below in this bag	1		2–6		1.5M USB wire	1	

ltem	Picture	Name	QTY	Check	ltem	Picture	Name	QTY	Check
1-6-1		40*10 Fan	1		2-7	0	5015 Air blower	1	
1-6-2		40*11 Cooling fin	1		2-8	<b>St</b>	Y axis belt bearing support	1	
1-6-3	٠¢٠	Fan cover	1		2-9		Seven parts below in this bag	1	
1-6-4	2 All	M3*45 Screw 2pcs M3 Spacer 8pcs	1		2-9-1	•	Z axis Limit switch fixed plate	2	
1-7		Screw bag include below screws	1		2-9-2	8	Y axis motor support	1	
1-7-1		M3*18 screw 52pcs	1		2-9-3	£.	Y axis Limit switch fixed plate	1	
1-7-2	<b>N</b>	M3 Nut 64pcs	1		2-9-4		Y axis belt fixation clamp	2	


ltem	Picture	Name	QTY	Check	ltem	Picture	Name	QTY	Check
1-7-3		M8 Nut 16pcs M8 Spacer 12pcs	1		2-9-5		Guide rod back up plate	6	
1-7-4	金融	M4*8 screw 28pcs M4*14 screw 4pcs	1		2-10	2	Side support plate	2	
1-7-5	M	M3*30 screw 14pcs	1		2-11	Δ	Filament support plate	2	
1-7-6		M3*12 screw 15pcs	1		2–12		Filament support plate connecting plate	2	
1-7-7	ALL REAL	M2*12 screw 4pcs wing nut 4pcs Spring 4pcs	1		2–13		Screen baffle plate	1	
1-7-8	A Free	M3*25 screw 3pcs	1		2-14		Z axis motor support Plate	4	
1-8		Three parts below in this bag	1		2–15	·	8GB TF card and card reader	1	

ltem	Picture	Name	QTY	Check	Item	Picture	Name	QTY	Check
1-8-1	0	Wire 70CM	1		3-1	8	Bottom support plate	1	
1-8-2	ď,	Z axis Limit switch A 20CM X axis Limit switch B 55CM Y axis Limit switch C 70CM	3		3-2		Top support plate	1	
1-8-3		Pillar washer M3*7 4pcs Pillar washer M3*15 4pcs	8		3–3		Back plate	1	
1-9	No.	Three parts below in this bag	1		3-4		Front plate	1	
1-9-1		3mm*130mm Screwdriver	1		3-5		Support plate lock plate	2	
1-9-2	Γ	Hex wrench M1.5 Hex wrench M2 Hex wrench M2.5 Hex wrench M3	4		3-6		Z axis motor fixed plate	2	
1-9-3	Ĭ	Open spanner	1		3-7	8	Y axis motor fixed plate	1	

ltem	Picture	Name	QTY	Check	ltem	Picture	Name	QTY	Check
1-10	R	Four parts below in this bag	1		3-8		Extruder	1	
1-10-1	Ø	4.5M Winding pipe	1		3-9	-1)	X axis motor	1	
1-10-2		Belting	10		3-10		Yaxis motor	1	
1-10-3		R clip	3		3-11		Z axis motor	2	
1-10-4	XX	Locating piece	2		3-12		Linear bearing	7	

ltem	Picture	Name	QTY	Check	ltem	Picture	Name	QTY	Check
1-11		LCD 2004 screen	1		3-13		Guide rod 436mm 2pcs Guide rod 380mm 4pcs	6	
1-12	-	X Motor line 40CM Y Motor line 40CM Left Z Motor line 40CM Right Z Motor line 90CM Extruder Motor line 90CM	5		3-14	/	T type lead screw M8*345mm 2pcs Threaded rod M8*400mm 2pcs Threaded rod M8*150mm 1pcs	5	
1-13	<b>*</b>	Heat bed line 90CM	1		3-15	<b>W</b>	Power Supply	1	

### Please check printer parts quantity when you receive it .




Please be aware the screw holes is in red circles

### **Before Assembly**

#### Name and Qty. of printer parts

		-
ltem	Name of parts	QTY.
1	Bottom support plate	1
2	Top support plate	1
3	Side support plate	2
4	M3*18 Screw	12
5	M3 Nut	12







Please be aware the screw holes is in black circles

### **Before Assembly**



Name and Qty. of printer parts						
ltem	QTY.					
1 Step 1		1				
2	2 Support plate lock plate					
3 M3*18 Screw		4				
4	M3 Nut	4				






	Na	ame and Qty. of printer p	arts
	ltem	Name of parts	QTY.
Accomply Stop 1	1	Step 2	1
Assembly Step 4	2	Step 3	1
	3	M3*18 screw	4
	4	M3 Nut	4




### **Before Assembly**




Name and Qty. of printer parts						
ltem	Name of parts	QTY.				
1	1 Y axis belt bearing support					
2	Front plate	1				
3	M3*18 screw	2				
4	4 M3 Nut					



### **Before Assembly**






#### Name and Qty. of printer parts

ltem	Item Name of parts					
1	1 Step 6					
2	Y axis Guide rod	2				
3	Guide rod back up plate	4				
4	Linear bearing	4				
5	5 M3*18 Screw					
6	M3 Nut	4				



### **Before Assembly**

Assembly Step 7







#### Name and Qty. of printer parts

Item	Name of parts	QTY.
1	Hot bed fixed aluminum plate	1
2	Y axis belt fixation clamp	2
3	M4*14 screw	4

Attention: Leave vacancy between belt fixation clamp and hot bed fixed plate for belt positioning.

### **Before Assembly**





Attention: Please diagonally tighten the screws when all are in there place


### Name and Qty. of printer parts

## Assembly Step 9

Item Name of parts		QTY.
1	Belt	1

### **Before Assembly**


### **After Assembly**



Attention: Belt is for X&Y axis transmitting .Cut the length you need to each transmission shaft. The belt is 1.5m in total and 10-20cm left after installation.


### **Before Assembly**

Attention: Hot bed screws should be in the bottom, and wing nuts will keep the height of hot bed level as well as firming the hotbed.





### After Assembly




#### Name and Qty. of printer parts


ltem	em Name of parts	
1	Step 9	1
2	Hot bed	1
3	M3*30 Screw	4
4	Spring	4
5	M3 wing nut	4

### Attention: This hole is for Z axis guide rod positioning

### **Before Assembly**



### **After Assembly**




#### Name and Qty. of printer parts

GM3\*18

M3\*12

Item	Name of parts	QTY.
1	Step 10	1
2	Z axis motor	2
3	Z axis motor fixed plate	2
4	Z axis motor support Plate	4
5	Z axis Limit switch fixed plate	2
6	Z axis Limit switch A 20CM	1
7	M3*18 Screw	10
8	M3 Nut	10
9	M3*12 Screw	8

#### **Before Assembly**



3


M3\*25 Screw

3

#### Assembly Step 13 Name and Qty. of printer parts Name of parts Item QTY. 1 Step 11 1 2 Step 12 1 3 1 Right Z axis nut support M3\*18 4 Guide rod back up plate 2 5 Z axis Guide rod 380mm 2 6 M3\*18 screw 2 **Before Assembly** 7 2 M3 Nut 8 Z axis Guide rod:380mm




· .....




#### Name and Qty. of printer parts

ľ	tem	Name of parts	QTY.
	1 Step 13		1
	2	T type lead screw 345mm	2


Attention: loose the jackscrew of elastic coupling to place T lead screw to the bottom, then tighten the jackscrew.



### Before disassembly




### After disassembly





After disassembly

Loose M4\*6 screws first, then separate extruder from L black aluminum parts, remember to keep the screws.



### **Before Assembly**






#### Name of QTY. of printer part

Item	Name of parts	QTY.
1	Extruder taken from Step 16	1
2	40*10 Fan	1
3	40*11 Cooling fin	1
4	Fan cover	1
5	M3*45 Screw	2
6	M3 Spacer	6-8

### **Before Assembly**






#### Name of QTY. of printer part

Item	Name of parts	QTY.
1	Step 15	1
2	Black Aluminum taken from Step 16	1
3	M4*8 Screw	12

Attention: Install M4\*6 screw. Tighten M6 Screw on the throat with spanner till extruder is not loose. Name of QTY. of printer part

Item	Name of parts	QTY.
1	Step 17	1
2	Step 18	1
3	M4*16 We taken from Step 16	1

#### Before Assembly






#### Name of QTY. of printer part


Item	Name of parts	QTY.
1	Step 19	1
2	5015 Air blower	1
3	Wind mouth	1
4	₩3*18 screw	2

### **Before Assembly**





Name of QTY. of printer part

Item	Name of parts	QTY.
1	Belt	1
2	M3≭18 screw	2
3	M3 Nut 4	4



Attention: Belt is for X,Y axis transmitting . The length of belt is 1.5m in total. Normally there'll be 10-20cm left after installation.








#### Name of QTY. of printer part

Item	Name of parts	QTY.
1	LCD 2004 screen	1
2	Pillar washer ∦3*7	4
3	Screen baffle plate	1
4	M3∗30 screw	4
5	M3 Nut	8

### **Before Assembly**



AttentionThis is the wiring diagram of power supply. 1, 2, 3 seperately represent the line of fire (brown),Zero line (blue), ground wire (yellow). 4,5, 6 represent negative pole (black) (-);7,8,9 represent the positive pole (red) (+).**To avoid danger , please assure the installation is correct .** 



M3\*12

Name	of	QTY.	of	printer	part
------	----	------	----	---------	------

Name of parts

Step 22

Power Supply 12V

M3\*12screw

QTY.

1

1

3

Red circles stand for the power screw holes


### **After Assembly**

Item


1

2

3




### **Before Assembly**





#### **Before Assembly**




Attention: Please use the corresponding wire , especially motor wire & limited switch wire.

NO.	Option	Length (mm)
1	Power supply wire	700mm
2	X motor wire	<b>400mm</b>
3	Y motor wire	<b>400mm</b>
4	Left Z motor wire	400mm
5	Right Z motor wire	900mm
6	X limited switch wire	550mm
7	Y limited switch wire	700mm
8	Z limited switch wire	200mm
9	Extruder motor wire	900mm
10	4010 Fan wire	1100mm
11	5015 Blower wire	1100mm
12	Heating pipe wire	1000mm
13	Extruder thermistor wire	1000mm
14	Hotbed wire	900mm
15	X Belt	1500
16	Y Belt	1500mm
17	Screen wire	500mm

#### Length of A8 Components Wire


### Attention: Please connect the electronics wire to each components correspondingly.





Name	of	QTY.	of	printer	part
------	----	------	----	---------	------


Item	Name of parts	QTY.
1	Filament support plate	2
2	Filament support plate connecting plate	2
3	Threaded rod 150mm	1
4	N8 screw	4
5	₩3*18 screw	4
6	M3 Nut	4





















# **Installation Complete**

 Congratulations ! You have just made yourself a 3D printer !

 Please contact your 3D printer supplier if any puzzles during using process.

 Thank you for choosing our products, we will always provide you more services.